




## Engine Pertinent Records Package

CFM56-3C1

Engine S/N 725105  
W/O: 5086C



FAA REPAIR STATION Q6GR293Y, EASA REPAIR STATION EASA.145.6500

14080 S.W. 143 Ct Miami, FL 33186, P:(305).254.0034, F: (305).254.0037



## TABLE OF CONTENTS

- FAA FORM 337
- LLP SHEET
- NON-INCIDENT STATEMENT

**FAA REPAIR STATION Q6GR293Y, EASA REPAIR STATION EASA.145.6500**


**14080 S.W. 143 Ct Miami, FL 33186, P:(305).254.0034, F: (305).254.0037**



# FAA FORM 337

**FAA REPAIR STATION Q6GR293Y, EASA REPAIR STATION EASA.145.6500**

**14080 S.W. 143 Ct Miami, FL 33186, P:(305).254.0034, F: (305).254.0037**

 <b>MAJOR REPAIR AND ALTERATION</b> <b>(Airframe, Powerplant, Propeller, or Appliance)</b> <small>U.S. Department of Transportation Federal Aviation Administration</small>	Form Approved OMB No. 2120-0020 11/30/2007	Electronic Tracking Number
	<b>For FAA Use Only</b>	

**INSTRUCTIONS:** Print or type all entries. See Title 14 CFR §43.9, Part 43 Appendix B, and AC 43.9-1 (or subsequent revision thereof) for instructions and disposition of this form. This report is required by law (49 U.S.C. §44701). Failure to report can result in a civil penalty for each such violation (49 U.S.C. §46301(a))

<b>1. Aircraft</b>	Nationality and Registration Mark	Serial No.	
	Make	Model	Series
<b>2. Owner</b>	Name <i>(As shown on registration certificate)</i>	Address <i>(As shown on registration certificate)</i> Address _____ City _____ State _____ Zip _____ Country _____	

**3. For FAA Use Only**

4. Type		5. Unit Identification			
Repair	Alteration	Unit	Make	Model	Serial No.
<input type="checkbox"/>	<input type="checkbox"/>	AIRFRAME	_____	<i>(As described in item 1 above)</i>	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	POWERPLANT	CFM INTERNATIONAL	CFM56-3C1	725105
<input type="checkbox"/>	<input type="checkbox"/>	PROPELLER			
<input type="checkbox"/>	<input type="checkbox"/>	APPLIANCE	Type		
			Manufacturer		

**6. Conformity Statement**

A. Agency's Name and Address	B. Kind of Agency
Name TURBINE ENGINE SOLUTIONS Address 14080 SW 143 COURT City MIAMI State FLORIDA Zip 33186 Country UNITED STATES OF AMERICA	<input type="checkbox"/> U.S. Certificated Mechanic <input type="checkbox"/> Foreign Certificated Mechanic <input checked="" type="checkbox"/> Certificated Repair Station <input type="checkbox"/> Certificated Maintenance Organization
	<input type="checkbox"/> Manufacturer <b>C. Certificate No.</b> <b>Q6GR293Y</b>

**D.** I certify that the repair and/or alteration made to the unit(s) identified in item 5 above and described on the reverse or attachments hereto have been made in accordance with the requirements of Part 43 of the U.S. Federal Aviation Regulations and that the information furnished herein is true and correct to the best of my knowledge.

Extended range fuel per 14 CFR Part 43 App. B <input type="checkbox"/>	Signature/Date of Authorized Individual  Martin Cordero <span style="float: right;">3/15/2023</span>
--	--

**7. Approval for return to Service**

Pursuant to the authority given persons specified below, the unit identified in item 5 was inspected in the manner prescribed by the Administrator of the Federal Aviation Administration and is  Approved  Rejected

BY	<input type="checkbox"/>	FAA Flt. Standards Inspector	<input type="checkbox"/>	Manufacturer	<input type="checkbox"/>	Maintenance Organization	<input type="checkbox"/>	Persons Approved by Canadian Department of Transport
	<input type="checkbox"/>	FAA Designee	<input checked="" type="checkbox"/>	Repair Station	<input type="checkbox"/>	Inspection Authorization	Other <i>(Specify)</i>	

Certificate or Designation No. <b>Q6GR293Y</b>	Signature/Date of Authorized Individual Martin Cordero <span style="float: right;">3/15/2023</span>
---	--

## NOTICE

*Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.*

### 8. Description of Work Accomplished

*(If more space is required, attach additional sheets. Identify with aircraft nationality and registration mark and date work completed.)*

**WORK ORDER: 5086C**

**MODEL: CFM56-3C1**

**ETT: 63,472.0**

**ENGINE SERIAL NUMBER: 725105**

**ETC: 41,318**

Nationality and Registration Mark

Date

**SUBJECT ENGINE WAS REMOVED FOR LLP REPLACEMENT; THE FOLLOWING WAS ACCOMPLISHED:**

- I. **FAN AND BOOSTER MODULE (ATA 72-00-21):** was removed and inspected in-situ.
  
- II. **HPC ROTOR MODULE (ATA 72-00-31):** was removed as a module, disassembled, cleaned, inspected, repaired, balanced, and assembled.
  - i. Removed and replaced damaged HPC blades on Stg's 3,5,6,7,8 and 9 with overhauled condition units.
  - ii. Removed and replaced HPC 4-9 Spool with overhauled units.
  
- III. **HPC FRONT STATOR ASSEMBLY (ATA: 72-00-32):** was removed as a module, partially disassembled, cleaned, inspected, repaired, and assembled.
  - i. Installed overhauled Stage's 1 thru 5 Honeycomb seals.
  - ii. Match grinded all honeycomb sections.
  
- IV. **HPC REAR STATOR (ATA: 72-33-00):** was removed as a module, disassembled, cleaned, inspected, repaired, and assembled.
  - i. Installed overhauled Stage's 6 thru 8 Honeycomb seals.
  - ii. Match grinded all honeycomb sections.
  
- VI. **COMBUSTION ASSY (ATA 72-41, -42):** was removed as a module, disassembled, cleaned, inspected, repaired, and assembled.
  - i. Installed FWD Inner Nozzle Support in overhauled condition.
  - ii. Installed overhauled Condition Combustion Chamber.
  - iii. Installed a set of Bench Checked Fuel Nozzles.
  - iv. Installed overhauled HPT Inner Stationary Seal
  
- VII. **HPT NOZZLE MODULE (ATA 72-00-51):** was removed and replaced with serviceable condition module.
  - i. Installed HPT Outer Stat. Seal in serviceable condition.

N/A  Additional Sheet Are Attached

## NOTICE

*Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.*

### 8. Description of Work Accomplished

*(If more space is required, attach additional sheets. Identify with aircraft nationality and registration mark and date work completed.)*

--	--

**WORK ORDER: 5086C**

Nationality and Registration Mark

Date

**MODEL: CFM56-3C1**

**ENGINE SERIAL NUMBER: 725105**

**ETT: 63,472.0**

**ETC: 41,318**

- VIII. **HPT ROTOR MODULE (ATA 72-00-52):** was removed, cleaned, inspected, assembled, balanced and installed in serviceable condition.
- IX. **HPT SHROUD AND STAGE 1 LPT NOZZLE ASSEMBLY (ATA 72-00-53):** Removed, partially disassembled, cleaned, inspected, assembled, and installed in serviceable condition.
  - i. Removed and replaced Full set of HPT Shrouds with overhauled condition units.
  - ii. Matched Grind Shrouds to HPT Blades.
- V. **LPT MAJOR MODULE (ATA 72-00-03):** was removed and inspected on situ.
- VI. **IGB MODULE (ATA 72-00-61):** was removed as a module, partially disassembled, cleaned, inspected, repaired, balanced, and assembled.
- IX. **AGB MODULE (ATA 72-00-63):** was removed and replaced with serviceable condition unit (SB 72-1129).
- X. **MAIN LINE BEARINGS:** was removed, cleaned, inspected and installed in serviceable condition.
- XI. **ACCESSORIES:**
  - i. Installed 5<sup>th</sup> STG Bleed Air valve in overhauled condition.
  - ii. Installed overhauled MEC.
  - iii. Installed bench checked Fuel Pump.
  - iv. T-2 Sensor was installed in overhauled condition.
  - v. CIT Sensor was inspected and tested.
  - vi. VSV Actuators was inspected and tested.
  - vii. Fuel Gear Motor was installed in repaired condition.
  - viii. TCC Valve was installed in overhauled condition.
  - ix. Flexible Shaft Assemblies were installed in new condition.
  - x. Master Ball screw Actuator was inspected and tested.
  - xi. Ball screw Actuator Assemblies was inspected and tested.
  - xii. T495 thermocouples wiring harness was inspected and tested.

**ACCOMPLISHED TEST NO. 10 ON WING PER 71-00-00 PER BOEING B737 AIRCRAFT MANUAL & ON-WING 365 DAY PRESERVATION PER (AMM) MOST CURRENT REVISION AND FOUND ALL PARAMETERS TO BE WITHIN SERVICEABLE LIMITS. (ENGINE RUN WAS PERFORMED BY XTREME AVIATION LLC FAA CRS # 4XAR847C) POST MPA RUN BORESCOPE INSPECTION WAS COMPLETED BY TURBINE ENGINE SOLUTIONS, INC AND FOUND TO BE WITHIN ACCEPTABLE LIMITS.**

**THE AIRCRAFT ENGINE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION AND IS APPROVED FOR RETURN TO SERVICE.**

**PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER WORK ORDER NO. 5086C**



# LIFE LIMITED PARTS SHEET

FAA REPAIR STATION Q6GR293Y, EASA REPAIR STATION EASA.145.6500

14080 S.W. 143 Ct Miami, FL 33186, P:(305).254.0034, F: (305).254.0037



## Life Limited Parts Time/Cycle Record

**ENG. MODEL:** CFM56-3C1  
**ENG. SERIAL NO.:** 725105  
**TSN:** 63,472.00  
**CSN:** 41,318  
**WORK ORDER:** 5086C  
**DATE:** \_\_\_\_\_

NOMENCLATURE	PART NO.	SERIAL NO.	TOTAL HOURS	CAT A	CAT B	CAT C	CAT 7B22	CAT 7B24	CAT A LIMIT	CAT B LIMIT	CAT C LIMIT	7B22 LIMIT	7B24 LIMIT	TOTAL CYCLES	CR CAT A	CR CAT B	CR CAT C
<b>FAN ROTOR MODULE</b>																	
BOOSTER SPOOL	335-009-306-0	BB443963	N/A	4,249	15,101	1		0	30,000	30,000	30,000			19,351	10,649	10,649	10,649
FAN STG. 1 DISK	335-014-511-0	BB443943	N/A	4,249	15,101	1		0	30,000	24,900	20,100			19,351	7,555	6,271	5,062
FWD FAN SHAFT	335-006-414-0	DB687841	N/A	4,249	15,101	1		0	30,000	30,000	30,000			19,351	10,649	10,649	10,649
<b>HPC ROTOR MODULE</b>																	
HPC FRONT SHAFT	1275M37P02	GWN0FG5L	N/A	0	9,920	1			20,000	20,000	20,000			9,921	10,079	10,079	10,079
HPC SPOOL 1-2	1589M66G02	GWN0FGTH	N/A	0	9,920	1			20,000	20,000	20,000			9,921	10,079	10,079	10,079
HPC STG. 3 DISK	1590M59P01	XAEH5322	N/A	0	9,920	1			20,000	20,000	20,000			9,921	10,079	10,079	10,079
HPC SPOOL 4 - 9	1588M89G03	GWN0F45K	N/A	0	0	0	13521	777	20,000	20,000	15,800	20,000	20,000	0	5,702	5,702	4,504
HPC SEAL - CDP	1319M25P02	GFF5EJ70	N/A	0	2,719	4285			20,000	18,000	15,000		16,800	7,004	11,265	10,139	8,449
<b>HPT ROTOR MODULE</b>																	
HPT FWD SHAFT	1385M90P04	XAEL9057	N/A	2,328	4,430	1			20,000	17,300	17,000			6,759	12,549	10,855	10,667
HPT FWD AIR SEAL	1282M72P05	XAEM5116	N/A	2,328	4,430	1			20,000	15,800	15,100			6,759	12,063	9,529	9,107
HPT DISK	1475M29P03	GWN0HR8D	N/A	2,328	4,430	1			20,000	18,500	16,600			6,759	12,881	11,915	10,691
HPT REAR SHAFT	1864M91P02	TMT1AR44	N/A	2,328	4,430	1			20,000	20,000	20,000			6,759	13,241	13,241	13,241
<b>LPT MAJOR MODULE</b>																	
LPT STG. 1 DISK	301-331-126-0	PA210507	N/A	2,328	4,430	1			25,000	25,000	25,000			6,759	18,241	18,241	18,241
LPT STG. 2 DISK	301-331-227-0	PA234822	N/A	2,328	4,430	1			25,000	25,000	25,000			6,759	18,241	18,241	18,241
LPT STG. 3 DISK	301-331-322-0	PA232247	N/A	2,328	4,430	1			25,000	25,000	25,000			6,759	18,241	18,241	18,241
LPT STG. 4 DISK	301-331-429-0	BB457890	N/A	4,249	15,101	1			25,000	25,000	25,000			19,351	5,649	5,649	5,649
LPT CONICAL SEAL	305-056-116-0	DA703150	N/A	2,328	17,686	1			25,000	25,000	25,000			20,015	4,985	4,985	4,985
LPT SHAFT	301-330-067-0	LA084197	N/A	4,249	15,101	1			30,000	30,000	30,000			19,351	10,649	10,649	10,649
LPT STUB SHAFT	301-330-626-0	BC063220	N/A	12,551	4,430	1			25,000	25,000	25,000			16,982	8,018	8,018	8,018

The above data was obtained from engine records supplied by the previous owners, repair agencies and operators of the engine.

Notes: \* Denotes replaced disks at this shop visit.

Form: TESI 1039C

Approved by: \_\_\_\_\_

18-Jul-2023

Date





# NON-INCIDENT

**FAA REPAIR STATION Q6GR293Y, EASA REPAIR STATION EASA.145.6500**

**14080 S.W. 143 Ct Miami, FL 33186, P:(305).254.0034, F: (305).254.0037**



December 06, 2018

**STATEMENT OF NON-INCIDENT / ACCIDENT**

**Subject:** Boeing 737-400 Aircraft MSN 23991  
CFM56-3B2 Engine S/N 725105  
CFM56-3B2 Engine S/N 725103  
GTCP85-129H APU S/N P-100049  
Nose Landing Gear S/N CPT2671ETM  
Left Main Landing Gear S/N XC93327  
Right Main Landing Gear S/N XC92276

**To:** Whom it may concern

This letter certifies that the subject aircraft, engines, landing gears, APU and associated components were operated by NewGen Airways for 6378 hours and 36 minutes and 2561 cycles, as detailed below, for the purpose of relocation ferry flights from Bangkok, Thailand to Tainan Airport, Taiwan.

During the relocation ferry flights detailed below, the Aircraft and installed Engines, Landing Gears, APU and associated components were not involved in any incident or accident, nor were they subjected to any severe stress or heat or salt water immersion, or otherwise exposed to corrosive agents outside normal operations, and were not operated by or acquired from any military or governmental organization.

**Relocation Ferry Flights**

DATE	ROUTE	HOURS	CYCLES	THRUST	LOG PAGE
04-Dec-18	DMK-TNN	3:07	1	CAT C	013306
	<b>TOTALS:</b>	<b>3:07</b>	<b>1</b>		

<b>Final Status after ferry:</b>	<b><u>TSN</u></b>	<b><u>CSN</u></b>
Aircraft MSN 23991	68254:10	43870
Engine S/N 725105	63472:00	41318
Engine S/N 725103	65017:07	41448

I certify that the information above is true and correct to the best of my knowledge.

  
\_\_\_\_\_  
Mr. Pichest Issara  
Quality Assurance Engineering Manager  
Technical Department  
NewGen Airways.  
Thailand.